Contents

Acknowledgments ..... **VII**

Preface ..... **IX**

About the Author ..... **XI**

Foreword by Glenn Beall ..... **XIII**

Foreword by Louis Maresca ..... **XV**

Foreword by Joe McFadden ..... **XIX**

1 Introduction **1**

1.1 Causes of Plastics Failure 1

1.2 The Holistic Approach 2

1.2.1 The Four Wheels 4

1.2.1.1 Material 4

1.2.1.2 Design 5

1.2.1.3 Processing 5

1.2.1.4 Tooling 6

1.2.2 Assembly and Secondary Operations 6

1.3 References 6

2 Plastic Materials **7**

2.1 Introduction 7

2.2 Polymer Fundamentals 7

2.2.1 Polymer 8

2.2.2 Polymer Chain 8

2.2.3 Thermoplastics and Thermosets 9

2.2.3.1 Thermoplastic Types—Amorphous and Semicrystalline . . 9
2.2.3.2 Thermosets 10
2.2.4 Thermoplastic Molecular Arrangements 12
2.2.4.1 Blends, Alloys, and Copolymers 13
2.2.4.2 Commercial Plastics—Not Just Polymers 13
2.2.5 Average Molecular Weight of Plastic Resins 14
2.2.5.1 Molecular Weight 14
2.2.5.2 Molecular Weight and Mechanical Properties 16
2.2.5.3 Molecular Weight and Viscosity 17
2.2.5.4 Melt Flow Rate 18
2.2.6 Injection Molding of Thermoplastic Materials 19
2.2.6.1 Heating Amorphous and Semicrystalline Materials 19
2.2.6.2 All Materials Are Amorphous During Injection 20
2.2.6.3 Degradation 20
2.2.7 Plastic Properties 21
2.2.7.1 A Word of Caution about Using MFI to Predict Flow 21
2.2.8 Color Fundamentals 23
2.2.8.1 Color Measurement 24
2.3 “Plastics Are Not Metals” 30
2.3.1 Color, Gloss, and Aesthetics 30
2.3.2 Long Term Stress 33
2.3.3 Plastics and Chemical Resistance 34
2.3.3.1 Physical Effect 36
2.3.3.2 Chemical Resistance 36
2.3.4 Physical Properties—Plastics vs. Metals 38
2.3.4.1 Temperature Dependent Behavior of Plastics vs. Metals 39
2.3.5 Latent Defects 40
2.4 Choosing the Right Plastic for Your Application 41
2.4.1 The Commercial Plastics Family 41
2.4.2 Material Selection Process 42
2.4.2.1 Morphology 44
2.4.2.2 Thermal and Mechanical Properties 45
2.4.2.3 Special Properties 45
2.5 Thermoplastic Elastomers and Overmolding 48
2.5.1 TPE Family 48
2.5.2 Compatible Materials 50
2.6 References 50

3 Design 53

3.1 Introduction 53

3.2 Robust Design 54
3.2.1 Cost 54
3.2.1.1 Legitimate Costs 54
3.2.1.2 Avoidable Costs 55
3.2.1.3 Beyond Avoidable Costs 55
3.2.2 Performance, Manufacturability, and Costs 57
3.2.3 Purely Physical Requirements 58
3.2.4 Chemical and Environmental Requirements 58
3.2.5 Agency and Regulatory Requirements 59
3.2.6 Tooling and Molding Related Requirements 59
3.2.6.1 Wall Thickness 59
3.2.6.2 Knit or Weld Lines 76
3.2.6.3 Boss and Rib Height Considerations 80

3.3 Plastics Structural Calculations 83
3.3.1 Stress or Strain? 83
3.3.2 Long Term Strains 87
3.3.2.1 Warpage 89
3.3.2.2 Plastic Screws 89
3.3.2.3 Force Fit Assemblies 91
3.3.2.4 Tolerance Stack Up Issues 92
3.3.3 Change in Physical Properties with Rate of Loading 95
3.3.4 Metal Inserts 95
3.3.5 Draft 101
3.3.6 Gate Location and Effect of Location 103
3.3.7 Orientation 105
3.3.8 Wear of Plastics 108

3.4 Thin Walls, Structural Foam, and Gas Assisted Molding 109
3.4.1 Thin Wall Molding 109
3.4.1.1 Wall Thickness Variation 111
3.4.1.2 Rib Thickness 112
3.4.2 Structural Foam Molding 112
3.4.3 Gas Assisted Molding 113

3.5 References 113

4 Tooling Considerations 115
4.1 Introduction 115
4.2 Injection Molding Tool Family 115
4.2.1 Two Plate Molds 116
4.2.2 Three Plate Molds 118
4.3 Mold Elements 120
4.3.1 Steel Selection 120
4.3.2 The Feed and Vent System 123
4.3.2.1 Sprue and Sprue Bushing 123
4.3.2.2 Runner 123
4.3.2.3 Gates 132
4.3.2.4 Vents 136
4.3.3 Creating Undercuts 140
4.3.3.1 By Pass Shut Off 140
4.3.3.2 Angle Pin or Finger Cam 141
4.3.3.3 Hydraulic Cylinders or Solenoids 142
4.3.3.4 Floating "A" Plate 142
4.3.3.5 Collapsible Core 143
4.3.3.6 Lifters 143
4.3.3.7 Loose Piece Insert 144
4.3.3.8 General Notes on Side Action 144
4.3.4 The Ejector System 145
4.3.4.1 Ejector Pins and Blades 145
4.3.4.2 Ejector Sleeves 146
4.3.4.3 Stripper Plate Ejection 147
4.3.4.4 Air Poppet Valve 147
4.3.4.5 Factors Influencing Ease of Ejection 148
4.3.4.6 Guided Ejection 148
4.3.5 Special Case: Reverse Mold 149
4.3.6 Thermal Management 150
4.3.6.1 Cooling Insert and Baffles 152
4.3.6.2 Bubblers 152
4.3.6.3 Thermal Pin 153
4.3.6.4 Coolant Flow Requirements 154
4.4 Steel Safe Condition 156
4.5 Reviewing Mold Designs 156
4.5.1 Information Needed 156
4.5.2 Title Block 157
4.5.3 Core Plan View 157
4.5.4 Cavity Plan View 157

4.5.5 3D Rendering of Part 159
4.5.6 Mold Design Checklist 159
4.6 References 159

5 Processing 161

5.1 The Molding Machine 161
5.1.1 Injection Molding Machine Components 162
5.1.2 The Feed System 162
5.1.2.1 Screw Details 164
5.1.2.2 Clamp Tonnage and Capacity 165
5.1.2.3 Intensification Ratio 166
5.2 The Injection Molding Cycle 167
5.2.1 Filling or Velocity Stage 168
5.2.2 Packing 168
5.2.3 Cooling and Ejection 168
5.3 Process Capability 169
5.4 Basic Controls in Injection Molding 169
5.4.1 Drying Time, Temperature, and Drying of Air 169
5.4.1.1 Background 169
5.4.1.2 The Drying Process 171
5.4.1.3 Control of Drying Time 173
5.4.1.4 Control of Dryness 173
5.4.2 Melt Temperature 174
5.4.3 Mold Temperature 175
5.4.4 Fill Time and Shear Rate 176
5.4.5 Packing Pressure and Time 177
5.4.6 Gate Freeze Time 178
5.4.7 Cooling Time 178
5.4.8 Residence Time 178
5.5 Common Processing Issues 180
5.5.1 Poor Drying 181
5.5.2 Hesitation 181
5.5.3 Knit Line Strength and Appearance 184
5.5.3.1 Venting 185
5.5.3.2 Melt Temperature 186
5.5.3.3 Injection Speed 186
5.5.3.4 Packing Pressure 186
5.5.3.5 Mold Temperature 186
5.5.3.6 Mold Surface 187
5.5.3.7 Material 187
5.5.3.8 Putting It All Together through a DOE 187

5.5.4 Jetting 190
5.5.5 Poor Venting 192
5.5.6 Poorly Designed Gates, Runners, and Sprue 193
5.5.7 Mold Heating 196
5.5.7.1 Ignorance 196
5.5.7.2 Poor Controls and Monitoring 197
5.5.7.3 Intentional Overriding of Established Process Parameters 197
5.5.7.4 Effects of Running the Mold Too Hot 197
5.5.7.5 Effects of Running the Mold Too Cold 198
5.5.8 Gate Blush 200
5.5.9 Flow Marks, Gloss, and Texture Variation 202
5.5.10 Record Grooving 204
5.5.11 Warping 205
5.5.11.1 Non-Uniform Shrinkage 205
5.5.11.2 Poor Ejection 206
5.5.12 Flashing and Short Shots 206
5.5.13 Sink Marks 207
5.5.14 Scuffing 207
5.5.15 Read Through and Shadows 208
5.5.16 Unequal Shrinkage in Cross Direction 208
5.5.17 Use of Shrink Fixture 209
5.6 Scientific Molding 209
5.6.1 Traditional Molding vs. Scientific Molding 209
5.6.2 Details of the Process 210
5.6.3 Establishing the Optimum Process 212
5.6.3.1 Step 1: The Viscosity Curve and the Injection Speed 212
5.6.3.2 Step 2: Balancing the Cavities 213
5.6.3.3 Step 3: Pressure Drop Study 214
5.6.3.4 Step 4: Setting the Pack and Hold Pressures 215
5.6.3.5 Step 5: Setting the Hold Time 216
5.6.3.6 Step 6: Setting the Cooling Time 217
5.7 Putting It All Together—Processing Parameters Recording 218
5.7.1 Proper Recording of the Process 218
5.7.2 Ongoing Control of the Process 220
5.7.3 Allowable Changes to the Processing Parameters 224
5.8 References 224

6 Secondary Operations ... 225

6.1 Introduction ... 225

6.2 Ultrasonic Assembly ... 226
6.2.1 Theory ... 226
6.2.1.1 Hysteresis Heating ... 226
6.2.1.2 Energy for Ultrasonic Welding ... 227
6.2.2 Generation of Vibration ... 228
6.2.3 Ultrasonic Welding System Components ... 229
6.2.3.1 Control of Power and Total Energy Provided to the Welded Surface ... 230
6.2.3.2 Details of the Subcomponents ... 231
6.2.4 Types of Ultrasonic Welding ... 235
6.2.5 Welding Polymers ... 236
6.2.5.1 Other Factors Affecting Ease of Welding ... 238
6.2.6 Design Factors ... 239
6.2.6.1 Joint Types ... 239
6.2.6.2 Part Design ... 241
6.2.6.3 Fixture Design ... 244
6.2.6.4 Important Welding Parameters ... 245

6.3 Heat Staking ... 250
6.3.1 Heat Staking Machines ... 252
6.3.2 Insert Height and Required Torque ... 255

6.4 References ... 256

7 Part and Tool Costs ... 257

7.1 Introduction ... 257

7.2 Part and Assembly Costs ... 257
7.2.1 Elements of a Plastic Part Cost ... 257
7.2.1.1 Cost of Molded Parts ... 258
7.2.1.2 Cost of Bought Parts ... 258
7.2.1.3 Secondary Operations ... 258
7.2.1.4 Profit ... 258
7.2.2 Overall Cost to Customer ... 259
7.2.3 Determination of Shop Rates, Overhead Costs on Resin and Bought Parts, and Margin ... 260
7.2.4 Determination of Cycle Times ... 260
7.2.5 Putting It All Together ... 261

7.3 Tool Costs ... 263
7.3.1 Tool Specifications ... 263
7.3.2 Tool Costing Sheet ... 264

8 Six Sigma Techniques in Plastics 267

8.1 Introduction 267

8.2 Brief History 268

8.3 Evolution of Six Sigma 268

8.4 DMAIC 270
8.4.1 Define 271
8.4.2 Measure 271
8.4.3 Analyze 271
8.4.4 Improve 271
8.4.5 Control 272

8.5 Design for Six Sigma and DMADV 272
8.5.1 Define 272
8.5.2 Measure 274
8.5.3 Analyze 275
8.5.4 Design 275
8.5.4.1 Failure Mode and Effects Analysis (FMEA) 275
8.5.4.2 Poka Yoke 277
8.5.4.3 Conventional Tools Used in Design Phase: Simulation ... 277
8.5.4.4 Some Common Poka Yoke Tools for the Design Process .. 279
8.5.4.5 Some Other Commonly Used Tools 280
8.5.5 Verify 283

8.6 Going Beyond Just Making Good Products 283
8.6.1 Kano Analysis 283
8.6.2 Breaking the Paradigm 285
8.6.3 BHAGS (Pronounced “Be Hags”): Big Hairy Audacious GoalS 286

8.7 References 288

9 Further Reading and Reference Material 289

9.1 Introduction 289

9.2 Materials 289
9.2.1 Step 1: Search across Suppliers 290
9.2.2 Step 2: Search within Suppliers 291
9.2.3 RoHS, REACH, UL, and Other Standards 292
9.2.3.1 RoHS 292
9.2.3.2 REACH 292
9.2.3.3 UL 94 Standard for Tests for Flammability of Plastic Materials for Parts in Devices and Appliances 293

9.3 Design 293
9.3.1 Structural Calculations Including Snaps and Gears 293

9.3.2 High Performance Optical Parts 294
9.3.3 Living Hinge 294
9.3.4 Brittle and Ductile Failures 294
9.3.5 Thin Wall Molding 295
9.3.6 Structural Foam 295
9.3.7 Gas Assisted Molding 295
9.3.8 Two Shot Molding 296
9.3.9 Pad Stamping 296
9.3.10 Plating 296
9.3.11 In-Mold Decoration 297
9.3.12 Ultrasonic Welding 297
9.4 Tooling 297
9.4.1 Classes of Molds 297
9.4.2 Tool Polish 297
9.4.3 Texture 298
9.4.4 Total Tolerance 298
9.4.5 Sprue, Gate, and Vent Design 298
9.5 Processing 299
9.6 Simulation and Analysis 299
9.6.1 Simulation 299
9.6.2 Design Checking and Design for Performance 299
9.7 Failure Analysis Tools 300
9.8 Six Sigma and Statistics 301
9.8.1 Basic Statistics 301
9.8.2 Design of Experiments (DOE) 302
9.8.3 Process Capability 302
9.8.4 Six Sigma Tools 302
9.9 References 303

Index 305