

Contents

Preface to the Second Edition	VII
-------------------------------------	-----

Preface to First Edition	IX
--------------------------------	----

1 Introduction to Scientific Processing	1
--	----------

1.1 The Evolution and Progress of Injection Molding	1
1.2 The Molding Process	2
1.3 The Three Types of Consistencies Required in Injection Molding	2
1.4 Scientific Processing	6
1.5 The Five Critical Factors of Molding	7
1.5.1 Part Design	8
1.5.2 Material Selection	8
1.5.3 Mold Design and Construction	9
1.5.4 Machine Selection	9
1.5.5 Molding Process	9
1.6 Concurrent Engineering	10
1.7 Variation	10

2 Properties of Polymers and Plastics That Influence Injection Molding	13
---	-----------

2.1 Polymers	13
2.2 Molecular Weight and Molecular Weight Distribution	15
2.3 Polymer Morphology (Crystalline and Amorphous Polymers)	17
2.4 Role of Morphology in Injection Molding	22
2.4.1 Differences in Shrinkage between Amorphous and Crystalline Materials	22
2.4.2 Melt Processing Range	22
2.4.3 Mold Filling Speed	23

2.4.4	Mold Temperatures	24
2.4.5	Barrel Heat Profile	24
2.4.6	Screw Recovery Speeds	25
2.4.7	Nozzle Temperature Control	25
2.4.8	Cooling Times	26
2.4.9	Mechanical Properties	26
2.4.10	Optical Clarity	26
2.5	Exceptions of Morphology Rules to Polyolefins	27
2.6	Thermal Transitions in Polymers	28
2.6.1	Relationship between the Glass Transition Temperature and Post Mold Shrinkage	32
2.7	Shrinkage of Polymers in Injection Molding	36
2.8	The Plastic Pressure–Volume–Temperature (PVT) Relationship	39
2.8.1	Importance of Plastic Density in Injection Molding	40
2.8.2	Residence Time and Maximum Residence Time of a Plastic ...	41
2.8.3	Plastic Datasheets	43
2.9	References	45
3	Polymer Rheology	47
3.1	Viscosity	47
3.2	Newtonian and Non-Newtonian Materials	49
3.3	Viscosity in Polymer Melts	50
3.4	Effect of Temperature on Viscosity	54
3.5	Velocity and Shear Rate Profiles	55
3.6	Application to Injection Molding	56
3.6.1	Flow Imbalance in an 8-Cavity Mold	57
3.6.2	Racetrack Effect in a Part with Constant Thickness	59
3.6.3	Stress Build-Up in Molded Parts	59
3.6.4	Warpage Difference between Cavities	60
3.7	Solving Flow Imbalances Using Melt Rotation Techniques	60
3.8	Fountain Flow	62
3.9	Effect of Fountain Flow on Crystallinity, Molecular Orientation, and Fiber Orientation	65
3.10	Characterization of Polymer Viscosity	66
3.11	References	67

4 Plastic Drying	69
4.1 Problems in Melt Processing Related to the Presence of Moisture	71
4.1.1 Degradation of Plastic	71
4.1.2 Presence of Surface Defects	71
4.2 Hygroscopic Polymers	75
4.3 Drying of Plastics	77
4.3.1 Drying Temperatures and Times	77
4.3.2 Relative Humidity and Dew Point	79
4.3.3 Air Flow Rate	80
4.4 Equipment for Drying Plastics	80
4.4.1 Oven Dryers	80
4.4.2 Hot Air Dryers	81
4.4.3 Desiccant Dryers	81
4.4.4 Classifications Based on the Location of the Dryer	81
4.5 Determination of the Amount of Moisture	82
4.5.1 The Glass Slide Technique (TVI Test)	82
4.5.2 The Karl-Fischer Titration Method	83
4.5.3 Electronic Moisture Analyzer	83
4.5.4 Measurement of the Dew Point	84
4.6 'Overdrying' or Overexposure to Drying Temperatures	85
4.7 Cautions	92
4.8 Prevention of Overexposure to Longer Drying Times	92
4.9 Overdrying Controller	93
4.10 References	94
5 Common Plastic Materials and Additives	95
5.1 Classification of Polymers	95
5.2 Commercially Important Plastics	97
5.2.1 Polyolefins	97
5.2.2 Polymers from Acrylonitrile, Butadiene, Styrene, and Acrylate	98
5.2.3 Polyamides (PA)	99
5.2.4 Polystyrenes (PS)	100
5.2.5 Acrylics	101
5.2.6 Polycarbonates (PC)	101
5.2.7 Polyesters	101
5.2.8 Polyvinyl Chloride (PVC)	101
5.2.9 Polyoxymethylene (POM or Acetal)	102
5.2.10 Fluoropolymers	103

5.3	Additives	103
5.3.1	Fillers	104
5.3.2	Plasticizers	104
5.3.3	Flame Retardants	104
5.3.4	Anti-aging Additives, UV Stabilizers	105
5.3.5	Nucleating Agents	105
5.3.6	Lubricants	106
5.3.7	Processing Aids	106
5.3.8	Colorants	106
5.3.9	Blowing Agents	106
5.3.10	Other Polymers	107
5.4	Closing Remarks	108
5.5	Reference	108

6 Injection Molding and Molding Machines 109

6.1	The History of Injection Molding	109
6.2	Injection Molding Machines and Their Classifications	110
6.3	Machine Specifications	112
6.3.1	Clamp Force (Tonnage)	113
6.3.2	Shot Size	113
6.3.3	Screw Diameter and L/D Ratio	113
6.3.4	Plasticating Capacity	114
6.3.5	Maximum Plastic Pressure	114
6.4	The Injection Molding Screw	114
6.5	Screw Designs	117
6.6	The Check Ring Assembly	118
6.7	Intensification Ratio (IR)	119
6.8	Obtaining Intensification Ratios	121
6.9	Selecting the Right Machine for the Mold	122
6.9.1	Physical Size of the Mold	122
6.9.2	Calculating the Required Machine Tonnage for a Mold	124
6.10	The Rule of Thumb for Tonnage Is Only an Estimate	126
6.10.1	Percentage Shot Size Used and Number of Shots in the Barrel	127
6.10.2	Residence Time of the Material in the Barrel	130
6.10.3	Practical Methods to Find Percentage Shot Size, Shots in a Barrel, and Residence Time	130
6.10.4	Residence Time Distribution	131

7 Scientific Processing, Scientific Molding, and Molding Parameters	133
7.1 Introduction	133
7.1.1 Process Robustness	135
7.1.2 Process Consistency	135
7.2 The 11+2 Plastic Injection Molding Machine Parameters	138
7.3 Process Outputs	141
7.4 What Scientific Molding and Scientific Processing Are Not	142
7.5 The Injection Molding Cycle	143
7.5.1 Injection, Pack, and Hold	143
7.5.2 Speed and Pressure	145
7.5.3 Pressure Limited Process	146
7.5.4 Decoupled Molding SM	146
7.5.5 Intensification Ratio (IR)	147
7.5.6 Screw Speed	148
7.5.7 Back Pressure	150
7.5.8 Cycle Time	151
7.6 References	152
8 Process Development Part 1: the 6-Step Study – Exploring the Cosmetic Process	153
8.1 Introduction	153
8.2 Introduction to Process Development	153
8.3 Premolding Setup	156
8.4 Storage and Drying of Resin	156
8.4.1 Plastic Drying	157
8.5 Machine Selection	159
8.6 Importance of Adding Charge Delay Time	160
8.7 Filling in Injection: Weight or Volume?	161
8.8 Setting of the Melt Temperatures	162
8.9 Setting Mold Temperatures	165
8.10 Process Optimization – the 6-Step Study	165
8.10.1 Step 1: Optimization of the Injection Phase–Rheology Study ...	165
8.10.2 Procedure to Determine the Viscosity Curve at the Molding Machine	169
8.10.3 How to Use this Information	171
8.10.4 Cautions and Exceptions	173
8.10.5 Profiling of Injection Speeds	173

8.10.6 When a Short Shot Sticks	174
8.10.7 Selecting Melt Temperature for Viscosity Graphs	176
8.10.8 Step 2: Determining the Cavity Balance – Cavity Balance Study	177
8.11 Reasons for Cavity Imbalance	180
8.11.1 Determining the Cause of Cavity Imbalances	184
8.11.2 Calculating Cavity Imbalance	184
8.11.3 Acceptable Level of Cavity Imbalance	185
8.11.4 Step 3: Determining the Pressure Drop – Pressure Drop Studies	187
8.12 Effect of Pressure Drop on the Pack and Hold Phase	194
8.12.1 Step 4: Determining the Cosmetic Process Window – Process Window Study	195
8.13 Relationship between Cavity Balance and Process Windows	202
8.14 The Pack and Hold Pressure Rule Not to Be Used	202
8.14.1 Step 5: Determining the Gate Seal Time – Gate Seal Study	203
8.15 Differentiating between the Pack and the Hold Phase	206
8.16 Hot Runner and Valve Gated Molds	210
8.16.1 Step 6: Determining the Cooling Time – Cooling Time Study	210
8.16.2 Optimization of Screw Rotation Speed	213
8.16.3 Why to Not Use the Rule of Thumb	214
8.17 Optimization of Back Pressures	215
8.18 The Cosmetic Scientific Process	216
8.18.1 Post Mold Shrinkage Studies	216
8.18.2 Procedure to Measure Shrinkage	219
8.19 Recommended Mold Function Qualification Procedure	220
8.20 Recommended Adjustments to Maintain Process Consistency and Robustness	221
8.21 Process Documentation	222
8.22 References	223

9 Process Development Part 2: Exploring the Dimensional Process via the DOE **225**

9.1 Parameters in Injection Molding	226
9.1.1 Design of Experiments: Definition	228
9.2 Terminology	230
9.2.1 Factor	230
9.2.2 Response	231

9.2.3	Level	231
9.2.4	Designed Experiment	231
9.3	Relationships between the Number of Factors, Levels, and Experiments	232
9.4	Balanced Arrays	234
9.5	Interactions	235
9.6	Confounding or Aliasing	238
9.7	Randomization	240
9.8	Factorial Experiments	241
9.9	Data Analysis	241
9.9.1	Tornado Charts	243
9.9.2	Contour Plots	244
9.9.3	Prediction Equation	245
9.9.4	Process Sensitivity Charts	246
9.10	Using the Results from DOE	247
9.10.1	Process Selection	247
9.10.2	Cavity Steel Adjustment	248
9.10.3	Process Adjustment Tool	249
9.10.4	Setting Process Change Tolerances	249
9.10.5	Reducing Inspection	249
9.11	The Dimensional Process Window (DPW)	250
9.12	Selections of Factors for DOEs	252
9.13	Analysis of Variance (ANOVA)	257
9.14	Collecting Shots for a Quality Check	258
9.15	Choosing the Highs and Lows for DOEs from the Process Window	259
9.16	DOE Application to Optimize Pack and Hold Times	260
9.17	Setting Acceptable Machine Tolerances and Alarms during Production	265
9.18	Summary	266
10	Mold Qualification Flowchart, Production Release, and Troubleshooting	269
10.1	Mold Qualification Flowchart	269
10.1.1	Mold Function Qualification Procedure	271
10.1.2	Mold and Part Quality Qualification Procedure	271
10.2	Mold Qualification Checklist	271

10.3	Process Documentation	272
10.3.1	Process Sheet	272
10.3.2	Waterline Diagrams	273
10.3.3	Mold Temperature Maps	274
10.3.4	Setup Instructions	275
10.3.5	Operator Instructions	275
10.4	Documentation Books	276
10.5	Qualification Production Runs	277
10.6	Mold Specific Troubleshooting Guide	277
10.7	Molding Startup and Shutdown	278
10.7.1	Purging	278
10.7.2	Startup of a Molding Machine	279
10.7.3	Shutdown of a Molding Machine	280
10.8	Troubleshooting	280
10.9	Important Equipment and Tools for Qualifications and Troubleshooting	283
10.10	Common Defects, Their Causes, and Prevention	284
10.10.1	Splay: What is it? How to get rid of it?	285
10.10.2	Defects in Molding	287

11 Role of Mold Cooling, Venting, and Regrind in Process Development **293**

11.1	Mold Cooling	293
11.1.1	Number of Cooling Channels	294
11.1.2	Reynolds Number of the Coolant Flow	294
11.1.3	Type of Coolant	295
11.1.4	Series and Parallel Cooling	296
11.2	Venting	297
11.2.1	Dimensions of the Vent	298
11.2.2	Primary Vent Depths	299
11.2.3	Location of Vents	302
11.2.4	Forced Venting or Vacuum Venting	304
11.3	Regrind	305
11.3.1	Effect of the Molding Process on the Part Properties	305
11.3.2	Using Regrind	307
11.3.3	Batch and Continuous Processes of Incorporating Regrind	307
11.3.4	Estimating the Amount of Regrind from Different Generations	308

11.3.5 Effect of Regrind on Processing	311
11.3.6 Closing Remarks	311

12 Related Technologies and Topics **313**

12.1 Cavity Pressure Sensing Technology	313
12.1.1 Sensors and Output graphs	314
12.1.2 Types and Classification of Pressure Sensors	315
12.1.3 Use of Information from the Pressure Graphs	317
12.1.4 Controlling the Process with Cavity Pressure Sensors	319
12.1.5 Sensor Locations	321
12.2 Building a Knowledge Base	322
12.3 Concurrent Engineering in Injection Molding	324
12.3.1 The Product Designer	326
12.3.2 The Tooling Engineer	326
12.3.3 The Mold Designer and Mold Maker	327
12.3.4 The Material Supplier	327
12.3.5 The Process Engineer	328
12.3.6 The Quality Engineer	329
12.3.7 The Sales Team at the Molder	329
12.3.8 Mandatory for All Departments	330
12.3.9 Implementing Concurrent Engineering	330

13 Quality Concepts **333**

13.1 Basic Concepts	333
13.2 Histogram	334
13.3 Normal Distribution	335
13.4 Standard Deviation	336
13.5 Specification Limits and Standard Deviation	337
13.6 Capability Index	339
13.7 Process Capability	340
13.8 Statistical Quality Control (SQC) and Statistical Process Control (SPC)	342
13.9 References	342

Appendix A Materials Data Sheet **343****Appendix B Conversion Tables for Commonly Used
Process Parameters **349****

Appendix C Water Flow Tables	351
Appendix D Part Design Checklist	353
Appendix E Mold Design Checklist	355
Appendix F Mold Qualification Checklist	357
Appendix G Regrind Tables – Percentage of Regrind in Total Shot	359
Index	361