

Contents

Acknowledgments	V	
Preface	VII	
About the Author	IX	
Part 1: Plastics		
Polymers	3	CHAPTER 1
1.1 Plastics	3	
1.2 Molecular Bonds	4	
1.3 Functionality	6	
1.4 Polymerization	6	
1.4.1 Polycondensation	6	
1.4.2 Polyaddition	6	
1.5 Determination of the Molecular Weight of Polymers	7	
1.6 Thermoplastics	8	
1.6.1 Classification of Thermoplastics	8	
1.6.1.1 According to Their Molecular Structure: Morphology	8	
1.6.1.2 According to Their Molecular Chain Form	11	
1.6.1.3 According to the Position of Atoms in the Chain	12	
1.7 Properties and Characteristics of Plastics	13	
1.7.1 Thermal and Physical Behavior	13	
1.7.1.1 Rheology	13	
1.7.1.2 Elastic Deformation	13	
1.7.1.3 Viscosity	13	
1.7.1.4 Glass Transition Temperature (T_g)	15	
1.7.1.5 Melting Temperature (T_m)	16	
1.7.1.6 Thermoplastics Behavior	17	
1.7.1.7 Changes of State in Amorphous Materials	17	
1.7.1.8 Changes of State in Semi-crystalline Materials	18	
1.7.1.9 Behavior under Load	19	
1.8 A Brief History of Plastics	21	
1.8.1 1900–1930	22	
1.8.2 1950s	23	
1.8.3 1960s	24	
Thermodynamic Behavior of Plastics: PVT Graphs	25	CHAPTER 2
2.1 Thermodynamics	25	
2.2 PVT Graphs	25	
2.2.1 PVT Graphs Related to Amorphous and Crystalline Materials	25	

	2.2.1.1	Dosage Stage, Plastification, Melting	26
	2.2.1.2	Injection Stage, Filling the Mold or Cavities . . .	26
	2.2.1.3	Hold Pressure Stage	27
	2.2.1.4	Cooling Stage	27
	2.2.1.5	Influence of Injection Molding Parameters Reflected in PVT Graphs	30
	2.2.1.6	Crystallization Stages	33
CHAPTER 3	Burn Test		35
	3.1	Identification of Various Types of Plastics	35
	3.2	Recognition and Identification of Plastics by Burn Test	36
CHAPTER 4	Water and Plastics, a Difficult Friendship		37
	4.1	Exposure on Duty	37
	4.2	Water and Polymer in Molten State	38
	4.3	Water-Sensitive Plastics	38
CHAPTER 5	Acronyms for Some Plastics, Reinforced Plastics, and Rubbers		41
CHAPTER 6	General Features of Some of the Most Used Thermoplastics		46
	6.1	Polyolefins	46
	6.1.1	Polyethylene (PE)	46
	6.1.1.1	High Density Polyethylene (HDPE)	46
	6.1.1.2	Low Density Polyethylene (LDPE)	46
	6.1.1.3	Linear Low Density Polyethylene (LLDPE)	47
	6.1.1.4	Comparison of Different Structures of Polyethylenes	48
	6.1.2	Polypropylene (PP)	49
	6.1.2.1	PP Homopolymer Properties	49
	6.1.2.2	PP Copolymers	49
	6.1.3	Ethylene Vinyl Acetate (EVA)	50
	6.1.4	Ethylene Vinyl Alcohol (EVOH)	50
	6.2	Polyoxymethylene (POM)	50
	6.3	Polystyrenes (PS)	51
	6.3.1	PS General Purpose	51
	6.3.2	Medium or High Impact PS (HIPS)	52
	6.4	Acrylonitrile Butadiene Styrene (ABS)	52
	6.5	Blend ABS-PC	53
	6.6	Styrene Acrylonitrile (SAN)	53
	6.7	Acrylonitrile Styrene Acrylic Rubber (ASA)	54
	6.8	Polyamides (PA)	54
	6.9	Polyesters	56
	6.9.1	Polybutylene Terephthalate (PBT)	56
	6.9.2	Polyethylene Terephthalate (PET)	56

6.10	Polyphenylene Oxide (PPO)	57	
6.11	Polycarbonate (PC)	58	
6.12	Polymethylmethacrylate (PMMA)	58	
6.13	Liquid Crystal Polymer (LCP)	59	
6.14	Elastomers	59	
6.14.1	Thermoplastic Elastomer (TPE-V)	59	
6.14.2	Elastomer Thermoplastic Vulcanized (ETPV)	60	
6.14.3	Thermoplastic Copolymer Elastomer Ether Ester (TPC ET)	60	
6.14.4	Polyurethane (TPU)	61	
6.14.4.1	Composition	61	
6.15	Styrene Butadiene Copolymer (SBC)	62	
6.16	Ionomer	63	
6.17	Polyphenylene Sulfide (PPS)	63	
6.17.1	Properties	63	
6.17.2	Features	64	
6.18	Polysulfones	64	
6.18.1	Polyphenyl Sulfone (PPSU)	64	
6.18.2	Polyethersulfone (PESU)	64	
6.18.3	Polysulfone (PSU)	65	
Chemical Resistances		66	CHAPTER 7
7.1	Chemical Substances	66	
7.1.1	Ethers	66	
7.1.2	Alkalis	67	
7.1.3	Esters	67	
7.1.4	Ketones	68	
7.1.5	Aliphatic Compounds	69	
7.1.6	Halogenated Hydrocarbons	69	
7.1.7	Halogenated Compounds	69	
7.1.8	Amines	69	
7.1.9	Other Chemicals that May Attack Plastics	70	
Additives		74	CHAPTER 8
8.1	Stabilizers	74	
8.2	Lubricants	75	
8.3	Antioxidants	76	
8.4	UV Protection	76	
8.4.1	Absorbents	76	
8.4.2	HALS	76	
8.5	Plasticizers	76	
8.6	Antistatic Compounds	77	
8.7	Flame Retardants	77	
8.7.1	Combustion Mechanism of a Plastic	78	
8.7.1.1	Solid Phase	78	

8.7.1.2	Gaseous Phase	78
8.7.2	Some Types of Flame Retardants	79
8.8	Halogen-Free Flame Retardants	79
8.8.1	Halogens	79
8.8.2	Usual Names for Halogen-Free Materials	80
8.8.3	Contribution of Halogens in Plastics	80
8.8.4	Need for Alternatives to Halogenated Materials	80
8.9	Foaming Agents	81
8.10	Hydrolysis Stabilizers	81
8.11	Slips and Antiblocking	81
8.11.1	Slips	81
8.11.2	Antiblocking	81
8.12	Nucleating Agents	81
8.13	Compatibility Agents	82
8.14	Impact Modifiers	82
8.15	Fillers and Reinforcements	82
8.16	Mineral Additives	83
8.17	Antifriction Lubricants	84
8.18	Dyes and Pigments	84
8.19	Masterbatch	85
8.20	Applications	87
8.20.1	Action Mode	87
8.20.2	Addition Mode	87
8.20.3	Some Products	87
CHAPTER 9	Tests on Plastics	88
9.1	Mechanical Tests	88
9.1.1	Tensile Test ISO 527 1-2	88
9.1.2	Flexural Test ISO 178	89
9.1.3	Wear Resistance Test TABER ASTM D1044	90
9.1.4	Hardness Tests	90
9.1.4.1	Ball Pressure Hardness Test ISO 2039-1	90
9.1.4.2	Rockwell Hardness Test ISO 2039-2	90
9.1.4.3	Shore A and Shore D Hardness Test ISO 868 ..	91
9.1.5	Impact Charpy Test ISO 179 IZOD, ISO 180	92
9.1.5.1	Izod Test ISO 180	92
9.1.5.2	Charpy Test ISO 179	93
9.1.6	Scratch ASTM D3363	93
9.1.7	Compression Set Test	94
9.2	Thermal Tests	94
9.2.1	Definitions	94
9.2.2	Vicat Test ISO 306	95
9.2.3	HDT ISO 75	95
9.2.4	Hot Ball Pressure Test	96
9.2.5	Relative Temperature Index (RTI) Test	96

9.2.6	Coefficient of Linear Thermal Expansion (CLTE) Test	97
9.2.7	Flammability Test UL94	97
9.2.8	Limited Oxygen Index (LOI) Test ISO 4589 1.2	99
9.2.9	Incandescent Glow Wire IEC 60695-2-13 and 2-12	100
9.2.10	Glow Wire Ignition Test (GWIT) IEC 60695-2-13, 2-12 . . .	101
9.2.11	Glow Wire Flammability Test (GWFT) IEC 60695-2-12 . . .	101
9.2.12	Reaction to Fire: Classification	101
9.3	Electric Tests	102
9.3.1	Dielectric Strength ASTM D149 IEC 60243-1	102
9.3.2	Dissipation Factor ASTM D150 IEC 60250	102
9.3.3	Dielectric Constant ASTM D150 IEC 60250	102
9.3.4	Comparative Tracking Index (CTI) IEC 60112	102
9.3.5	Surface Resistivity (SR) ASTM D527 IEC 6009 3	103
9.3.6	Volume Resistivity (VR) ASTM D527 IEC 6009 3	104
9.4	Rheological Tests	104
9.4.1	Melt Flow Rate (MFR), MFI ISO 1133	104
9.4.2	MVI and MVR	105
9.5	Weathering	105
9.5.1	XW Weather-Ometer	106
9.5.1.1	Accelerated Weathering	106
9.5.1.2	Tests in Natural Environments	107
9.5.2	Radiation	107
9.6	Stress in Transparent Materials	108
9.6.1	Residual Stress Measurement in Transparent Materials .	108
9.6.2	Method	108
9.7	Colors: <i>Lab</i> System	109
9.8	Chemical Resistance and Stress Cracking	110
9.8.1	Electrical Properties	110
9.8.1.1	HWI: Hot Wire Ignition	110
9.8.1.2	HAI: High Ampere Arc Ignition	111
9.8.1.3	Time of Arc Resistance (TAR) ASTM D 495	111
9.8.1.4	HVAR: High Voltage Arc Resistance to Ignition	111
9.8.1.5	HVTR: High Voltage Arc Tracking Rate	111
9.8.1.6	CTI: Comparative Tracking Index	112
9.8.1.7	RTI: Relative Temperature Index	112

Properties of Plastics: Understanding Technical Data Sheets 113 **CHAPTER 10**

10.1	Density	114
10.2	Bulk Density	115
10.3	Flow Rates	115
10.3.1	Melt Volume Index (MVI)	115
10.3.2	Melt Flow Index (MFI)	116
10.4	Tensile Stress, Mechanical Resistance	117
10.5	Elastic Modulus and Tensile Modulus	118
10.6	Impact Resistance	119
10.7	Coefficient of Linear Thermal Expansion (CLTE)	120

	10.8 Vicat Softening Temperature	121
	10.9 Heat Deflection Temperature (HDT or HDTUL)	122
	10.10 Thermal Conductivity	123
	10.11 Hardness	124
	10.12 Surface Resistivity	124
	10.13 Heat Conductivity	125
	10.14 Yellow Card	125
	Part 2: Material Selection	
CHAPTER 11	Material Selection Checklist	129
	11.1 Technical Specifications	130
	11.2 Target Factor Values	131
CHAPTER 12	Material Selection	134
	Part 3: Injection: Machines and Processes	
CHAPTER 13	The Injection Molding Machine	161
	13.1 Clamping Unit	161
	13.1.1 Clamping Force	162
	13.1.2 Clamping Unit Systems	162
	13.1.2.1 Mechanical Toggle Clamping System	163
	13.1.2.2 Hydraulic Piston Clamping System	163
	13.1.2.3 Hydraulic Closure System for Large Tonnages .	164
	13.1.2.4 Servoelectric Clamping: Movements Made by Servomotors, Bearings, and High-Precision Screws	164
	13.1.3 Theoretical Clamping Force Required	165
	13.2 Injection Unit	166
	13.2.1 Injection Unit Characteristics	167
	13.2.1.1 <i>L/D</i> Ratio	167
	13.2.1.2 Compression Ratio (<i>K</i> -Ratio)	167
	13.2.1.3 Plasticizing Capacity	167
	13.2.2 Screw	167
	13.2.3 Barrels	168
	13.2.4 Screw Mechanism	168
	13.2.4.1 Screw Feeding Zone, Initial Zone	168
	13.2.4.2 Compression Zone, Solids Conveying Zone	168
	13.2.4.3 Nitrided Screw vs Bimetal Screw	169
	13.2.5 Check Valve Non-Return Tip	170
	13.2.6 Nozzle	171
	13.3 Which is the Right Machine?	173
	13.3.1 Factors to Consider for Choosing the Right Machine	173
	13.3.2 Clamping Force	174
	13.3.3 Residence Time of Material	175
	13.3.4 Injection Unit Size	175

13.3.5	Screw	176
13.4	Hardening Treatments for Injection Unit	176
13.5	The Pressure Multiplier	176

Key Parameters for Setting the Injection Molding Process ... 178 **CHAPTER 14**

14.1	Injection Speed	178
14.2	Ideal Filling Situation	179
14.2.1	Filling Speed Rate	182
14.2.1.1	Very High Speeds	182
14.2.1.2	Very Low Speeds	182
14.2.1.3	What Affects the Filling Speed?	182
14.3	Melt Temperature	184
14.4	Screw Peripheral Speed	185
14.5	Back Pressure	186
14.6	Injection Pressure	187
14.6.1	Holding Pressure Switching Systems	188
14.7	Holding Pressure	188
14.8	Holding Pressure Time	189
14.8.1	Cavity Pressure Drop	189
14.8.2	Injected Mass Weight Control	189
14.9	Mold Temperature	190
14.10	Dosage	192
14.11	Cushion	192

Correct and Optimized Methodology for the Process Start-up 193 **CHAPTER 15**

15.1	Requirements: Information Required	193
15.1.1	Material	193
15.1.2	Part	193
15.1.3	Mold	193
15.1.4	Machine	193
15.2	Possible Previous Calculations	194
15.3	Injection Machines Tune-up	196
15.3.1	Motion Setting	197
15.3.2	Injection Machine Start-up	198
15.3.2.1	Injection Fine-Tuning	198
15.3.3	Operative Method	201
15.3.4	Progressive Mold Filling	202
15.3.4.1	Progressive Filling Pressure Graphs	203
15.3.4.2	Hold Pressure Stage	203
15.3.5	Key Parameters of Process Control	204
15.3.6	Start-up and Fine-Tuning of Injection Machines—	
	Interpreting Graphs	205
15.3.6.1	Injection and Cavity Pressures	205
15.3.6.2	Effect of Parameters	205
15.3.6.3	Cavity Pressure	206

15.3.7	Effects of the Different Parameters	206
15.3.7.1	Mold Temperature	206
15.3.7.2	Melt Temperature	206
15.3.7.3	Part Temperature	207
15.3.7.4	Dosage Stroke	207
15.3.7.5	Back Pressure	207
15.3.7.6	Injection Speed	207
15.3.7.7	Holding Pressure	207
15.3.7.8	Material Viscosity	208
CHAPTER 16	Generic Recommendations for Injection Molding Conditions	209
CHAPTER 17	Mold Design Guide Recommendations	218
17.1	Metals Versus Steels for Molds	218
17.2	Runners	220
17.3	Types of Gates	224
17.3.1	Most Common Gates	224
17.4	Mold Cooling	226
17.5	Cooling System in Cores	226
17.6	Venting	227
17.6.1	Deep	227
17.6.2	Venting for Runners	228
17.6.3	Venting in Distribution Channels	229
17.6.4	Venting in Ejectors	229
17.7	Draft Angles	230
17.8	Shrinkage	230
CHAPTER 18	Gates: Types and Recommendations	231
18.1	Fan Edge	231
18.2	Submarine or Tunnel Gate	232
18.3	Pin Point Gate	232
18.4	Tab Gate	233
18.5	Sprue Gate or Direct Gate	234
18.6	Flash Gate	234
18.7	Outer Ring	235
18.8	Inner Ring	235
18.9	Overlaged Jump Gate	236
18.10	Pin Gate	236
18.11	Most Common Injection Points	237
18.12	Central Flow Distribution Channels	238
CHAPTER 19	Plastic Parts Design: Recommendations	239
19.1	Recommendations	239
19.1.1	Ribs and Reinforcements Designs	239

19.1.1.1	Relative Torsion Resistance vs Reference	240	
19.1.1.2	Deformation at Constant Load	241	
19.1.2	Tensile Stresses	241	
19.1.3	Thickness Design	242	
19.1.3.1	Changes in Thickness	243	
19.1.3.2	Homogeneous Thicknesses	243	
19.1.4	Sharp Corners and Radii	244	
19.1.5	Influence of the Notches in the Impact Resistance	245	
19.1.6	Slots and Undercuts	246	
19.1.7	Snap-Fit	247	
19.1.8	Rigidity	248	
19.1.9	Creep and Relaxation	248	
19.1.10	Tubular Frames, Screw Holes	249	
Injection: Some Practical Tips		250	CHAPTER 20
20.1	Inspection of Runners and Gates Systems	250	
20.1.1	Gate Depth, Width, and Length	250	
20.1.1.1	Defects Due to the Gates	251	
20.1.2	Gates and Runners Design	252	
20.1.3	Spiral Effect or Flow Distribution	253	
20.1.4	Nozzles in Processes with Hot Runners	254	
20.1.5	Cooling	254	
20.1.6	Purging or Cleaning of the Injection Unit	255	
20.1.7	Venting	255	
20.1.8	POM Foaming Test	257	
20.1.9	Surface Tension	258	
20.1.9.1	Contact Angle	259	
20.1.9.2	Industrial Methods for Activating the Surface or Increasing Surface Tension	260	
Part 4: Scientific Molding			
Scientific Molding or Injection by Advanced Methods		263	CHAPTER 21
21.1	Knowledge and Training are Tools for the Future	263	
21.2	The Process	263	
21.3	Some Concepts Related to Scientific Molding	264	
21.3.1	Molding Processor	264	
21.3.2	Science	264	
21.3.3	Intelligence	264	
21.4	Machine Inputs vs Process Outputs	265	
21.5	New Processing Tools	267	
21.6	Advanced Methods—Scientific Injection Molding Tools	269	
21.6.1	Relative Viscosity Analysis or In-Mold Rheology Test	269	
21.6.2	Delta P: Determination Method	274	
21.6.3	Process Window: Determination Method (for Holding Injection Pressure Phase)	276	
21.6.4	Gate Seal Study	278	

	21.6.5	Method and Analysis of Injection Pressure Losses along the Filling System	280
	21.6.6	Machine Portability	282
	21.6.7	Cavities Balance Study	283
	21.6.8	Study of Shear Stress at the Gates	284
	21.6.9	Blank Templates	287
	21.6.9.1	Gate Seal Study, Blank Template	287
	21.6.9.2	In-Mold Rheology, Blank Template	288
CHAPTER 22		Using Spreadsheets: Advanced Molding and Machine Portability	289
	22.1	Thermoplastic Processing by Injection—Advanced Manual	289
		Part 5: Failure Analysis	
CHAPTER 23		Process Under Control, Failure Analysis	303
	23.1	Points to Consider	303
	23.1.1	Clamping Unit	303
	23.1.2	Barrels	303
	23.1.3	Screws	303
	23.1.4	Nozzles	304
	23.1.5	Refrigeration System, Temperature Control in the Mold and the Machine	304
	23.1.6	Water Connection System in Molds	304
	23.1.7	Dryers and Dehumidifiers	305
	23.1.8	Grinders	306
	23.1.9	Hot Runner	307
	23.1.10	Thermoregulators	307
	23.1.11	Appearance Criteria	307
	23.1.12	Resin Handling	307
	23.2	Failure Analysis, Checks, and Optimizations	309
	23.2.1	Preliminary Investigation of Failures	309
	23.2.2	Process Optimization	310
	23.2.2.1	Radii	310
	23.2.2.2	Cold Slug	310
	23.2.2.3	Steps for Analysis of Problems Derived from Plastics Injection Molding Process	311
	23.2.3	Trials Injection Molding Parameters Template	314
CHAPTER 24		Typical Problems in Plastics Injection	315
	24.1	Lack of Drying or Dehumidification	315
	24.1.1	Materials Drying	316
	24.1.2	How to Properly Dehumidify	317
	24.2	Filling System	317
	24.2.1	Effects on the Quality of the Parts	318
	24.2.2	Runners System Design	319
	24.3	Proper Position of the Gate	319
	24.3.1	Consequences of a Non-correct Gate Location	320

24.3.2	Recommendations for Correct Gate Location	320
24.4	Hold Pressure Time Too Short	321
24.4.1	Hold Pressure Stage	321
24.4.2	Hold Pressure Time Too Short	321
24.5	Inadequate Melt Temperature	322
24.5.1	Incorrect Melt Temperature	322
24.5.2	Signs of Incorrect Melt Temperature	322
24.5.3	Correct Melt Temperature	322
	24.5.3.1 Melt Temperature Measurement	322
	24.5.3.2 30/30 Melt Temperature Measuring Method ..	323
24.6	Correct Mold Temperature	323
24.6.1	Incorrect Mold Temperature	324
24.6.2	Recommendations to Properly Adjust the Mold Temperature	324
24.7	Residues on Mold Surface	325
24.7.1	Types of Deposits	325
24.7.2	Mold Care	326
24.8	Excessive Material Drying	327

Defects in Injection Molded Parts 328 CHAPTER 25

25.1	Defects in Parts Manufactured by Thermoplastics Injection Molding	328
25.1.1	Sink Marks or Uncompensated Shrinkage	328
25.1.2	Streaks	330
	25.1.2.1 Streaks Caused by Burns	330
	25.1.2.2 Streaks Caused by Moisture	330
	25.1.2.3 Streaks Caused by Trapped Air	331
25.1.3	Weld Lines	332
25.1.4	Grooves, Vibrations, and Corona Effects	333
25.1.5	Gloss	333
25.1.6	Jetting	334
25.1.7	Spots and Markings near the Gate	335
25.1.8	Black Spots	335
	25.1.8.1 Process	335
	25.1.8.2 Machine	336
	25.1.8.3 Polymer	336
25.1.9	Inhomogeneous Material	336
25.1.10	Blushes near the Gate	337
25.1.11	Bubbles	337
25.1.12	Cracking	337
25.1.13	Delamination	337
25.1.14	Splay, Silver Marks	337
25.1.15	Warpage	338
25.1.16	Stress Cracking, ESC	338
25.1.17	Surface Scratching	338
25.2	Defects in Injection Molding and Painted Parts	338
25.2.1	Holes and Craters	338

25.2.2	Trapped Air	338
25.2.3	Part Molded with Stress	339
25.2.4	Cracks	339
25.2.5	Irregularities	340
25.2.5.1	Sinkings	340
25.2.5.2	Peaks/Crawling	340
25.2.5.3	Lack of Adhesion	341
25.3	Cross Cut Test	341
25.4	Defects in Chrome Plating on Plastic Parts	342
25.4.1	Defects	343
25.4.2	Peaks, Spots, Bubbles	343
25.4.3	Blisters	343
25.4.4	Adhesion	344

CHAPTER 26 Analysis of Real Cases 345

26.1	Broken Support Brackets	345
26.1.1	Drying of Material	345
26.1.2	Filling System Review and Optimization	347
26.2	Pulleys that Do Not Work	349
26.2.1	Radii	349
26.2.2	Material Selection	350
26.3	Broken Gears	350
26.4	Unfilled PC Cover	351
26.5	Dimensional Instability in Parts	352
26.6	Insufficient Filling	355
26.7	Several Problems with Polycarbonate	356
26.7.1	A Plastic Chair Full of Problems	356
26.7.1.1	Concentric Circular, Dark Area around the Gate	356
26.7.1.2	Weld Lines in the Back Chair Grill	356
26.7.1.3	Marks in the Cavity Gate	357
26.7.1.4	Streaks	357
26.8	Support Breaks	357
26.9	Deformation of ABS Part	359
26.10	Bimetallic Effect	360
26.11	Hesitation Effect (Flow Stoppage)	361
26.12	Gloss Caused by the Glass Fiber Reinforcement	363
26.13	Pressure-Limited Process: Always a Mistake to Avoid	365
26.14	Streaks in Transparent Polycarbonate	367
26.14.1	Dehumidifying	367
26.14.2	Back Pressure	368
26.14.3	Suction	368
26.14.4	Gate	368
26.15	Polyamide Parts Cannot Withstand the Assembly Stress	369
26.15.1	Gates	371

26.16	Unbalanced Runners	372
26.17	Material Degradation	372
26.18	TPU: The Unknown Thermoplastic	373
26.18.1	What is TPU?	374
26.18.1.1	Dehumidification	374
26.18.1.2	Back Pressure	375
26.18.1.3	Hold Pressure	375
26.18.1.4	Cooling and Total Time Cycle	376
26.19	Bubbles	376
26.19.1	Bubbles Caused by Trapped Air	377
26.19.2	Bubbles Caused by Vacuum	377
26.20	The Secret of the Night Shift Manager	378
26.20.1	Dryers and Dehumidifiers	379

Part 6: Reference Material

Reference Data Tables	383	CHAPTER 27
27.1	Maximum Residence Time	383
27.2	Usual Mold Temperatures	383
27.3	Shrinkage	384
27.4	Drying Conditions	384
27.5	Maximum Allowed Humidity Data	385
27.6	Recommended Depth Venting Channels	386
27.7	Mold and Melt Temperatures, Shear, and Other Properties	386
27.8	Maximum Peripheral Speeds	387
27.9	Density, Melt at Room Temperature	388
Bibliography	389	CHAPTER 28
Glossary	390	CHAPTER 29
Disclaimer	394	
Index	395	