

# Contents

<b>Preface to the Third Edition</b> .....	<b>V</b>
<b>1 Extrusion Machinery</b> .....	<b>1</b>
1.1 What is an Extruder? .....	1
1.2 Different Types of Extruders .....	2
1.2.1 Single Screw Extruders .....	2
1.2.2 Twin Screw Extruders .....	2
1.2.2.1 Co-Rotating Twin Screw Extruders .....	2
1.2.2.2 Counter-Rotating Twin Screw Extruders .....	3
1.2.3 Ram Extruders .....	4
1.3 Components of an Extruder .....	5
1.3.1 The Extruder Screw .....	5
1.3.2 The Extruder Barrel .....	5
1.3.3 The Feed Throat .....	6
1.3.4 The Feed Hopper .....	7
1.3.5 Barrel Heating and Cooling .....	7
1.3.6 Screw Heating and Cooling .....	9
1.3.7 The Breaker Plate .....	9
1.3.8 The Screen Pack .....	10
1.3.8.1 Screen Changers .....	11
1.3.9 The Extrusion Die .....	12
1.3.9.1 Coextrusion Dies .....	14
1.3.10 The Extruder Drive .....	14
1.3.10.1 Coupling between Motor and Gearbox .....	15
1.3.11 The Speed Reducer .....	16
1.3.11.1 Thrust Bearing Assembly .....	16
1.3.12 The Gear Pump .....	17
<b>2 Instrumentation and Control</b> .....	<b>19</b>
2.1 Instrumentation .....	19
2.2 Most Important Process Parameters .....	19
2.2.1 Melt Pressure .....	20
2.2.2 Pressure Transducers .....	21

2.2.3	Temperature Measurement . . . . .	22
2.2.4	Melt Temperature Measurement . . . . .	23
2.2.5	Barrel Temperature Measurement . . . . .	24
2.3	Temperature Control . . . . .	26
2.3.1	On-Off Control . . . . .	26
2.3.2	Proportional Control . . . . .	26
2.3.3	Fuzzy Logic Control . . . . .	28
2.4	Collection and Interpretation of Extrusion Process Data . . . . .	29
2.4.1	Introduction . . . . .	29
2.4.2	Vital Signs of the Extrusion Process . . . . .	29
2.4.2.1	Melt Pressure . . . . .	30
2.4.2.2	Melt Temperature . . . . .	35
2.4.2.3	Training . . . . .	44
2.4.3	Examples of Extrusion Problems Solved by Using a Data Acquisition System . . . . .	44
2.4.3.1	Variation in Stock Temperature . . . . .	44
2.4.3.2	Variation in Feed Housing Temperature . . . . .	46
2.4.3.3	Variation in Melt Pressure . . . . .	48
2.4.4	Process Optimization . . . . .	50
2.4.5	Temperature-Induced Dimensional Changes of Extrudate . . . . .	50
<b>3</b>	<b>Complete Extrusion Lines . . . . .</b>	<b>53</b>
3.1	Tubing and Pipe Extrusion Lines . . . . .	53
3.2	Film and Sheet Lines Using the Roll Stack Process . . . . .	54
3.3	Film Lines Using Chill Roll Casting . . . . .	55
3.4	Combination of Materials . . . . .	56
3.4.1	Coextrusion . . . . .	56
3.4.2	Extrusion Coating . . . . .	57
3.4.3	Extrusion Lamination . . . . .	58
3.5	Blown Film Lines . . . . .	59
3.6	Extrusion Compounding Lines . . . . .	59
3.7	Profile Extrusion Lines . . . . .	61
<b>4</b>	<b>Plastics and Their Properties Important in Extrusion . . . . .</b>	<b>63</b>
4.1	Thermoplastics and Thermosets . . . . .	63
4.2	Amorphous and Semi-Crystalline Plastics . . . . .	64
4.3	Liquid Crystalline Plastics (LCPs) . . . . .	66
4.4	Elastomers . . . . .	66
4.5	Flow Behavior of Plastic Melts . . . . .	67
4.6	Melt Index . . . . .	68
4.7	The Effect of Shearing . . . . .	69
4.8	Shear Thinning or Pseudoplastic Behavior . . . . .	69

4.9	Effect of Temperature on Viscosity .....	70
4.10	Viscous Heat Generation .....	71
4.11	Thermal Properties .....	71
4.11.1	Thermal Conductivity .....	72
4.11.2	Specific Heat and Enthalpy .....	72
4.11.3	Thermal Stability and Induction Time .....	73
4.11.4	Density .....	74
4.11.5	Melting Point .....	76
4.11.6	Glass Transition Temperature .....	76
<b>5</b>	<b>How an Extruder Works .....</b>	<b>77</b>
5.1	Solids Conveying .....	78
5.1.1	Gravity Induced Conveying .....	78
5.1.2	Drag Induced Conveying .....	81
5.1.3	Starve Feeding .....	82
5.1.4	Grooved Feed Extruders .....	83
5.2	Melting .....	85
5.2.1	Contiguous Solids Melting .....	85
5.2.2	Dispersed Solids Melting .....	86
5.3	Melt Conveying .....	89
5.3.1	Melt Temperatures .....	90
5.4	Mixing .....	93
5.4.1	Distributive Mixing .....	93
5.4.2	Mixing Sections .....	98
5.4.2.1	Distributive Mixing Sections .....	98
5.4.2.2	Dispersive Mixing Sections .....	102
5.5	Degassing .....	108
5.6	Die Forming .....	110
5.6.1	Size and Shape Changes .....	111
5.6.2	Tubing and Pipe Dies .....	114
5.6.3	Flat Film and Sheet Dies .....	117
5.6.4	Profile Dies .....	119
<b>6</b>	<b>How to Run an Extruder .....</b>	<b>123</b>
6.1	Introduction .....	123
6.2	Before Start-up .....	123
6.3	Getting Ready for a Run .....	124
6.4	Starting the Extruder .....	126
6.5	Actual Operation .....	128
6.6	Shutdown .....	129
6.6.1	Purging .....	129
6.7	Safety Issues .....	131
6.7.1	Heat .....	131

6.7.2	Moving Parts	131
6.7.3	Electrical	132
6.7.4	Weights	132
6.7.5	Pressure	132
6.8	Inspection and Training	133
<b>7</b>	<b>How to Troubleshoot Extrusion Problems</b>	<b>137</b>
7.1	Objectives	137
7.2	Prerequisites	137
7.2.1	Good Instrumentation	137
7.2.2	Good Understanding of the Process	138
7.2.3	Collect and Analyze Historical Data	138
7.2.4	Teamwork	138
7.3	Main Types of Problems	139
7.3.1	Output Problems	139
7.3.1.1	Low Extruder Output	139
7.3.1.2	Variation in Extruder Output	141
7.3.2	Appearance Problems	144
7.3.2.1	Lines	145
7.3.2.2	Die Drool	145
7.3.2.3	Discoloration and Degradation	145
7.3.2.4	Voids	147
7.3.2.5	Vent Flow	156
7.3.2.6	Air Entrapment	156
7.3.2.7	Gels	157
7.3.2.8	Poor Mixing	158
7.3.3	Functional Product Problems	160
7.3.4	High Melt Temperature	160
7.3.5	High Motor Load	161
7.3.6	Wear Problems	161
7.4	Systematic Problem Solving	163
7.5	Machine Troubleshooting and Maintenance	164
7.5.1	Check the Oil	165
7.5.2	Unusual Noises	165
7.5.3	Drive Motors and Belts	167
7.5.4	Spare Parts	167
7.5.5	Screw and Barrel	167
7.5.6	Extruder Maintenance Checklist	168
7.6	Troubleshooting Lists	171
<b>8</b>	<b>New Developments in Extrusion and Methods to Increase Efficiency</b>	<b>175</b>
8.1	General Trends	175
8.2	High-Speed Extrusion	175

8.2.1	Melt Temperature	175
8.2.2	Extruders without Gear Reducer	176
8.2.3	Energy Consumption	177
8.2.4	Change-over Resin Consumption	177
8.2.5	Change-over Time and Residence Time	177
8.3	Multi-Strand Extrusion	178
8.4	Reducing Material Cost	180
8.4.1	Low Cost Filler	180
8.4.2	Recycled Plastics	182
8.4.3	Foamed Plastics	182
8.4.4	Pre-compounded Material vs. In-house Compounding	183
8.4.5	Start-up, Change-over, and Shutdown	183
8.4.6	Polymer Processing Aids (PPA)	183
8.5	Increased Automation	186
8.6	Efficient Extrusion	186
8.6.1	Instrumentation	187
8.6.2	Data Acquisition	187
8.6.3	Feed Stock Variability	188
8.6.4	Flood Feeding versus Starve Feeding	188
8.6.5	Purging	189
8.6.5.1	Melt Displacement Behavior	190
8.6.5.2	Effect of Viscosity Differences	193
8.6.5.3	Effect of Color	194
8.6.5.4	Dynamic versus Static Purging Methods	195
8.6.5.5	Purging Agents	198
8.6.5.6	Practical Rules to Reduce Purge Times	198
8.6.6	Methods to Reduce Energy Consumption	200
8.6.6.1	Energy Requirement	200
8.6.6.2	Energy Cost per Kilogram	200
8.6.6.3	Energy Cost per Year	200
8.6.6.4	Barrel Cooling	200
8.6.6.5	Heat Loss at the Extrusion Die	201
8.6.6.6	Melt Temperature	201
8.6.6.7	Pre-Drying	202
8.6.6.8	Use of Filled Plastics	202
8.6.6.9	Tips to Reduce Energy Use in Extrusion	202
8.6.7	Flexible Manufacturing	203
8.7	Statistical Process Control (SPC) and Design of Experiments (DOE)	206
8.8	Causes of Process Variation	208
8.8.1	Melt Temperature Variation	208
8.8.2	Melting Related Instabilities	209
8.9	Grooved Feed and Grooved Barrel Extruders	209
8.9.1	Adjustable Grooved Feed Extruder	210
8.9.2	Grooved Barrel Extruders	210
8.10	The Rotary Channel Pump (RCP)	213

8.11	New Developments in Mixing and Screw Design .....	213
8.11.1	Elongational Mixing Devices .....	213
8.11.2	Barrier Screws with Elongational Mixing Action .....	214
8.11.3	Floating Sleeve Intermeshing Pin Mixer .....	215
8.11.4	High Heat Transfer (HHT) Screw Design Technology .....	216
8.11.5	The Single Screw Compounding Extruder (SSCE) .....	217
8.12	Fiber Reinforced Plastics .....	218
8.12.1	Conventional Methods to Make Fiber Reinforced Plastics .....	218
8.12.2	Nexus Technology .....	219
8.13	Conclusions .....	219
<b>9</b>	<b>Appendices .....</b>	<b>223</b>
9.1	Appendix 1: Recommended list for further reading .....	223
9.2	Appendix 2: Extrusion Theory .....	225
9.2.1	References .....	230
9.2.2	Nomenclature .....	230
<b>Index</b>	<b>.....</b>	<b>233</b>