

# Contents

Preface to the 2nd English Edition .....	V
Preface to the 3rd German Edition .....	V
Preface to the 2nd German Edition .....	V
Preface to the 1st German Edition .....	VI
<b>1      Introduction .....</b>	<b>1</b>
<b>2      Basic principles and terminology in thermoforming .....</b>	<b>5</b>
2.1     Process sequence .....	5
2.2     Positive and negative forming .....	6
2.3     Vacuum and pressure forming .....	8
2.3.1    Differences between vacuum and pressure forming .....	8
2.3.2    Application for pressure forming .....	9
2.4     Forming pressure, contour-molding pressure, and contour definition	10
2.5     Preblow, presuction, pressure equalisation, air injection .....	12
2.6     Chill marks and blemishes .....	13
2.6.1    Chill marks on positively formed parts .....	14
2.6.2    Chill marks on negatively formed parts .....	17
2.6.3    Causes of chill marks .....	19
2.6.4    Options for reducing chill marks .....	19
2.6.5    Results of chill mark formation .....	20
2.6.6    Use of typical wall-thickness distribution in chill marks with snaps on clamshell packages .....	21
2.6.7    Conclusions with regard to chill marks .....	22
2.6.8    Blemishes and markings .....	22
2.7     Wrinkle formation during thermoforming .....	23
2.7.1    Wrinkle formation sequence in positive forming .....	24
2.7.2    Wrinkle formation in negative forming .....	26
2.7.3    Wrinkle formation on surfaces .....	27

2.8	The tool set .....	28
2.9	Forming surface, intake surface, clamped edge .....	29
2.10	Downholder, upholder .....	30
2.11	Forming and stretching ratio .....	31
2.12	Draft angles .....	32
2.13	Vent cross-sections .....	33
2.14	Calculating wall thickness .....	33
<b>3</b>	<b>Semi-finished thermoplastic materials .....</b>	<b>35</b>
3.1	Elements and structure of thermoplastic materials .....	35
3.2	Absorption of moisture in semi-finished product .....	36
3.3	Response during heating .....	37
3.4	Expansion and sag .....	39
3.5	Forming temperature ranges .....	41
3.6	Friction properties in thermoforming .....	42
3.7	Contour definition .....	44
3.8	Molding shrinkage in thermoforming .....	45
3.9	Free shrinkage of semi-finished products .....	51
3.10	Effects of stresses in the extruded semi-finished product .....	55
3.11	Electrostatic charge .....	59
3.12	The visco-elastic properties of thermoplastic materials during thermoforming .....	60
3.13	Properties during cooling .....	62
3.14	Tolerances of semi-finished products .....	62
3.15	Manufacturing process for thermoplastic semi-finished products ....	63
3.16	Table for the thermoformer .....	67
3.17	Thermoplastics for thermoforming .....	71
3.17.1	Polystyrene (PS) .....	71
3.17.2	High-impact polystyrene (HIPS) .....	72
3.17.3	Styrene butadiene styrene block copolymer (SBS) .....	73
3.17.4	Oriented polystyrene (OPS) .....	74
3.17.5	Acrylonitrile butadiene styrene copolymer (ABS) .....	75
3.17.6	Acrylic styrene acrylonitrile copolymer (ASA) .....	76
3.17.7	Styrene acrylonitrile copolymer resin (SAN) .....	77
3.17.8	Polyvinylchloride (PVC-U) .....	78
3.17.9	Polyethylene, high-density (PE-HD) .....	79

3.17.10 Polypropylene (PP): Detailed presentation .....	80
3.17.11 Extruded polymethyl methacrylate (PMMA ex) .....	95
3.17.12 Cast polymethyl methacrylate (PMMA g) .....	96
3.17.13 Polycarbonate (PC) .....	98
3.17.14 Polyamide (PA) .....	99
3.17.15 Polyethylene terephthalate, PET: Detailed presentation .....	100
3.17.16 Polysulfone (PSU) .....	107
3.17.17 EPE and EPP foamed materials .....	108
3.17.18 Bioplastics in thermoforming .....	109
3.17.18.1 Biodegradable plastics from renewable raw materials .....	110
3.17.18.2 Non-degradable bioplastics .....	115
3.17.19 Multilayer, barrier and composite semi-finished materials ..	116
3.17.20 Other materials .....	125
3.17.21 Brand names .....	126
<b>4 Heating technology in thermoforming .....</b>	<b>127</b>
4.1 Radiant heaters .....	127
4.1.1 Heat-transfer concept with infrared radiation .....	127
4.1.2 Heat quantity transferred by radiation .....	129
4.1.3 Homogeneous heating with radiant heaters .....	135
4.1.4 Ceramic, quartz and halogen heaters in comparison .....	142
4.2 Reproducibility of heating results in radiant heaters .....	145
4.2.1 Assessing reproducibility .....	145
4.2.2 Compensation for uncontrollable external influences on the heating process .....	149
4.2.3 Power control and temperature control in heaters .....	150
4.3 Contact heaters .....	151
4.4 Convection heaters .....	153
4.5 Minimum heating time, effective heating time and residence time ...	154
4.5.1 Effect of heating time on thermoforming response .....	154
4.5.2 Positive effect of residence time .....	155
4.5.3 Negative effect of residence time .....	155
<b>5 Heaters in sheet-processing machines .....</b>	<b>157</b>
5.1 Basic principles of heating with isothermal control .....	158
5.1.1 Technical terminology .....	158
5.1.2 Details regarding temperature control with ceramic heat elements .....	161
5.1.3 Advantages of heating systems with closed-loop control provided by pilot heater elements .....	162

5.2	Joystick distribution of the heating pattern .....	162
5.3	Multi-positional control .....	164
5.4	Heater-element temperature control with superimposed position in percent .....	166
5.5	IR-sensor (pyrometer) for monitoring temperature and closed-loop control of heaters .....	167
<b>6</b>	<b>Heaters in automatic roll-fed machines .....</b>	<b>169</b>
6.1	General information .....	169
6.2	Heaters regulated by pilot heater elements in automatic roll-fed machines .....	170
6.2.1	Heater with longitudinal control of row temperatures .....	170
6.2.2	Heater panel with temperature control governing total array .....	171
6.2.3	Heater with transverse row control .....	172
<b>7</b>	<b>Heating multicoloured and preprinted materials using IR heaters .....</b>	<b>173</b>
7.1	General information .....	173
7.2	Selection of infrared heaters .....	173
<b>8</b>	<b>Thermoforming process on sheet-processing machines ....</b>	<b>177</b>
8.1	Positive forming .....	178
8.1.1	Positive forming with mechanical prestretching .....	178
8.1.2	Positive forming with preblow .....	179
8.1.3	Positive forming with preblow against a board .....	182
8.1.4	Positive forming with presuction and unreeling of the blister on the mold .....	183
8.1.5	Positive forming with presuction in a vacuum/pressure box ..	184
8.1.6	Application of corner blow nozzles with positive forming ...	185
8.2	Negative forming .....	186
8.2.1	Negative forming without plug-assist tool .....	186
8.2.2	Negative forming with plug-assist tool .....	187
8.3	Positive-negative forming .....	189
8.4	Twin-chamber method (3K method) .....	190
8.5	Twinsheet forming .....	191
8.5.1	Universal rules for twinsheet forming on series twinsheet forming machines .....	192
8.5.2	Twinsheet forming process, UA machine with hand loading ..	193
8.5.3	Machine versions for twinsheet forming .....	196

8.6	Adhesive lamination .....	198
8.6.1	General information .....	198
8.6.2	Lamination process .....	199
<b>9</b>	<b>Thermoforming process on automatic roll-fed machines, punching station with blade cut .....</b>	<b>203</b>
9.1	Concept of process sequence at the forming station .....	203
9.2	Machine equipment with an effect on the forming procedure .....	207
9.3	Selecting the correct forming procedure and tool configuration .....	208
9.4	Information regarding ways to influence wall thickness distribution ..	209
<b>10</b>	<b>Thermoforming process on automatic roll-fed machines, forming and punching tools with shear cuts .....</b>	<b>215</b>
10.1	Geometrical motion patterns of the forming and punching station ...	215
10.2	The special features of the mechanical cam control .....	217
10.3	Flow chart for a forming station using forming and punching tool with negative forming .....	218
10.3.1	Forming-air reduction .....	219
10.3.2	Downholder control .....	219
10.4	Flow chart for a forming station using forming and punching tool with shear cut for positive forming .....	220
<b>11</b>	<b>Special procedures using combined forming and punching tools in automatic roll-fed machines .....</b>	<b>221</b>
11.1	Applying linings to dimensionally stable containers .....	221
11.2	Labelling in the mold (IML In-Mold Labelling) .....	223
11.3	Forming and punching tool for rimless formed parts .....	226
11.4	Thermoforming hollow-base cups .....	227
11.5	Thermoforming with mold and countermold .....	228
<b>12</b>	<b>Thermoforming transparent parts .....</b>	<b>229</b>
12.1	Generally applicable rules for forming transparent parts .....	229
12.2	Special considerations for molding with sheet-processing machines ..	231
12.3	Special considerations for forming with automatic roll-fed machines ..	232
12.4	Sample procedures – Production of transparent parts .....	236
12.5	Special production process for transparent parts .....	241

<b>13</b>	<b>Thermoforming preprinted materials .....</b>	<b>243</b>
13.1	General information .....	243
13.2	Determining distortion-printing image .....	246
<b>14</b>	<b>Cooling the formed parts .....</b>	<b>251</b>
14.1	The demolding temperature .....	251
14.2	Influencing factors affecting cooling times .....	252
14.3	Cooling with the mold .....	253
14.4	Cooling with air .....	253
14.4.1	Current technology for air cooling in sheet-processing machines .....	255
14.4.2	Reducing the mold temperature in conjunction with colder cooling air .....	257
<b>15</b>	<b>Demolding .....</b>	<b>261</b>
<b>16</b>	<b>Stacking parts .....</b>	<b>265</b>
16.1	General information .....	265
16.2	Stacking formed parts with changing stacking lugs .....	271
<b>17</b>	<b>Finish-processing on thermoformed parts .....</b>	<b>273</b>
17.1	Separating, cutting .....	273
17.2	Deburring .....	276
17.3	Connecting .....	276
17.4	Recycling .....	278
<b>18</b>	<b>Punching thermoformed parts .....</b>	<b>279</b>
18.1	Blade cut .....	279
18.2	Shear cut .....	286
18.3	Comparisons of blade and shear cuts .....	293
18.4	Factors affecting the punching process .....	296
18.5	Angel-hair formation .....	297
18.5.1	Reduction of angel-hair formation with blade cut .....	301
18.5.2	Reduction in angel-hair formation with shear cut in forming and punching tool .....	302
18.6	Rough-edged cuts - Die drool .....	304
18.7	Punching forces .....	306

18.8	Conclusion .....	308
18.8.1	Blade-cut tools - Punching tools for separate punching station .....	308
18.8.2	Shear-cut tools for separate punching station .....	309
18.8.3	Forming and punching tools with blade cut .....	310
18.8.4	Forming and punching tools with shear cut .....	310
18.9	Related cutting procedures .....	311
<b>19</b>	<b>Decoration and thermoforming .....</b>	<b>315</b>
19.1	Illustrations .....	320
<b>20</b>	<b>Distortion in thermoformed parts .....</b>	<b>329</b>
20.1	Demonstrations of influences on distortion .....	329
20.2	Effect of thick points .....	331
20.3	Effect of tension in the semi-finished material .....	331
20.4	Distortion in a labelled formed part .....	332
20.5	Distortion of the clamped flange on a rectangular formed part .....	332
20.6	Distortion with anisotropic contraction .....	333
20.7	Conclusion, causes of distortion .....	334
20.8	Tips and information regarding distortion .....	335
<b>21</b>	<b>Thermoforming tools .....</b>	<b>337</b>
21.1	Terminology and definitions .....	337
21.2	Materials for the forming segment .....	338
21.3	Help for the tool material and version selection .....	342
21.4	Positive or negative forming? .....	343
21.5	Design configuration of the forming surface .....	344
21.6	Processing shrinkage: Who supplies the data? .....	348
21.7	Determining the size of the material .....	349
21.8	The substructure .....	350
21.8.1	Illustrations of structural concepts for tools .....	353
21.8.2	Adjustable substructures for sheet-processing machines .....	357
21.8.3	Difference between invariable format and adjustable substructure .....	358
21.9	Design details for thermoforming tools .....	359
21.9.1	Sidewall drafts .....	359
21.9.2	Surface roughness .....	360

21.9.3	Radii .....	363
21.9.4	Tool venting, air-discharge cross-sections .....	364
21.9.5	Cavities .....	368
21.9.6	Materials for plug-assist tools .....	368
21.9.7	Plug-assist tool contours for negative forming .....	370
21.9.8	Plug-assist tool for positive tools .....	374
21.10	Tool with undercut .....	375
21.10.1	Demolding undercuts without detachable parts .....	375
21.10.2	Detachable parts (slider) for demolding undercuts .....	375
21.11	Tool design for flat formed parts with low stretch .....	376
21.12	Tools for forming transparent parts .....	377
21.13	Tools for twinsheet forming .....	379
21.14	Tools for sheet-material hinges and snap couplings .....	385
21.15	Forming and punching tools with shear cut in automatic roll-fed machines .....	391
21.16	Forming and punching tools with knife cut in automatic roll-fed machines .....	394
21.17	Preventative maintenance on forming tools .....	407
<b>22</b>	<b>Temperature control for thermoforming tools .....</b>	<b>411</b>
22.1	General information .....	411
22.1.1	Temperature control terminology .....	411
22.1.2	Effects of tool temperature .....	412
22.1.3	When is it possible to dispense with tool temperature control? .....	412
22.2	Temperature-control media .....	413
22.3	Materials for thermoforming tools suitable for temperature control ..	414
22.4	Cooling-circuit versions .....	414
22.4.1	Examples of circuits in thermoforming machines .....	415
22.5	Cooling process .....	417
22.6	The cooling requirements of a thermoformed part .....	418
22.6.1	The enthalpy diagram .....	418
22.6.2	Enthalpy tables .....	419
22.6.3	Required cooling power for the tool .....	419
22.7	Design configuration of temperature-control system for a forming tool .....	420
22.7.1	Material quantity being cooled (material throughput) .....	421
22.7.2	Required cooling power during production .....	421

22.7.3	Cooling-water requirement for tool cooling .....	422
22.7.4	Contact surface required for the cooling water .....	423
22.7.5	Total length of cooling passages .....	424
22.7.6	Water velocity .....	424
22.7.7	Resulting pressure drop in the tool .....	425
22.7.8	Pressure loss when connecting the forming tool in the machine .....	427
22.8	Pressure loss in the machine's pipework .....	429
22.9	Pressure loss in overall temperature-control circuit .....	430
22.10	Testing the pumping capacity of the connected temperature control or cooling equipment .....	431
22.11	Assessing the test result .....	432
22.12	Design configuration options in heat transfer .....	433
22.13	The effects of air cooling on tool cooling .....	433
22.14	Preventive maintenance .....	434
<b>23</b>	<b>Energy consumption in thermoforming .....</b>	<b>437</b>
23.1	General information .....	437
23.2	Specific energy consumption in thermoforming .....	438
23.3	The share of energy costs as a proportion of the manufacturing costs for moldings .....	441
23.4	Options for reducing the specific energy consumption .....	444
23.4.1	Saving energy with electric drive units .....	446
23.4.2	Reduction of energy use in pressure forming .....	448
23.4.3	Reduction in the volume filled with compressed air, forming air reduction .....	449
23.4.4	Effects of pressure level .....	450
23.4.5	Reducing energy consumption during heating .....	454
23.4.6	Cost reductions with new vacuum pumps .....	457
23.4.7	Short cooling times reduce energy costs .....	457
23.4.8	Insulation of pipes? .....	459
23.4.9	Application of fresh-air coolers instead of refrigeration units with compressor .....	459
23.4.10	Offset heater starting time reduces price of power .....	459
23.4.11	Using energy reduction for extended downtime periods .....	460
23.4.12	Using the machine's basic settings .....	460
23.4.13	Regular periodic maintenance .....	460
23.4.14	Dynamic process optimisation .....	461
23.4.15	The energy consumption display .....	461
23.4.16	Energy consumption measurements in production .....	461

<b>24 Thermoforming faults .....</b>	<b>463</b>
24.1 Geometrical configuration errors on the formed part .....	463
24.2 Faults in the material .....	468
24.3 Selection of the correct thermoforming machine .....	470
24.4 Errors during installation of the thermoforming machine .....	471
24.5 Faults in the thermoforming tool .....	471
24.6 Errors during break-in new thermoforming tools .....	473
24.7 Errors during sample article inspections .....	474
24.8 Errors during heating with infrared radiators .....	474
24.9 Pipe and tube cross-sections for air and vacuum .....	475
24.10 Preventing wrinkle formation .....	476
24.11 Fault diagnosis in thermoforming .....	477
<b>Index .....</b>	<b>489</b>