

Contents

Preface	V
Acknowledgments	IX
1 Overview of Runners, Gates, and Gate Positioning	1
1.1 Primary Parting Plane Runners	1
1.2 Sub Runners	2
1.2.1 Cold Sub Runners	2
1.2.2 Hot Sub Runners	4
1.3 Hybrid Sub-Runner and Parting Line Runner	5
1.4 Gate Designs	5
2 Rheology and Melt Flow in an Injection Mold	7
2.1 Laminar vs. Turbulent Flow	8
2.2 Fountain Flow	10
2.3 Factors Affecting Viscosity	10
2.3.1 Common Viscosity Models	12
2.3.2 Non-Newtonian Fluids	14
2.3.3 Temperature	17
2.3.4 Pressure	17
2.4 Melt Compressibility	18
2.5 Melt Flow Characterization	19
2.5.1 Melt Flow Index	19
2.5.2 Capillary Rheometers	20
2.5.3 Nozzle Rheometers	25
2.6 Melt Flow in a Mold	26
2.6.1 Spiral Flow Molds	27
2.6.2 Injection Molding Simulation	28
2.6.3 Moldometer	30

3	Filling and Packing Effects on Material and Molded Part	33
3.1	Process Effects on Material Flow Characteristics	33
3.1.1	Melt Thermal Balance – Conductive Heat Loss vs. Shear Heating	33
3.1.2	Development of a Frozen Boundary Layer	36
3.2	Factors Affecting Plastic Material Degradation	42
3.2.1	Excessive Shear	42
3.2.2	Excessive Temperature	44
3.3	Effects of Mold Fill Rate on Fill Pressure	46
3.4	Post Filling or Packing Phase	47
3.4.1	Thermal Shrinkage as Plastic Cools	47
3.4.2	Compensation Flow to Offset Volumetric Shrinkage	48
3.4.3	Pressure Distribution During the Post Filling Phase	49
3.4.4	Gate Freeze-Off	50
3.5	Melt Flow Effects on Material and Molded Parts	51
3.5.1	Shrinkage	51
3.5.1.1	Volumetric Shrinkage	52
3.5.1.2	Orientation-Induced Shrinkage	54
3.5.2	Development of Residual Stresses and Warpage	58
3.5.2.1	Warpage and Residual Stress from Side-to-Side Shrinkage Variations	58
3.5.2.2	Warpage and Residual Stress from Global/Regional Shrinkage Variations	59
3.5.2.3	Warpage and Residual Stress from Orientation-Induced Shrinkage Variations	60
3.5.3	Physical Properties as Effected by Orientation	60
3.6	Annealing a Molded Part	61
3.7	Summary	61
4	Gate Positioning and Molding Strategies	65
4.1	Gate Positioning Considerations	65
4.2	Design and Process Strategies for Injection Molding	67
4.2.1	Maintain Uniform Wall Thicknesses in a Part	67
4.2.2	Use Common Design Guidelines for Injection Molded Plastic Parts with Caution	70
4.2.3	Avoid Flowing from Thin to Thick	71
4.2.4	Establish a Simple Strategic Flow Pattern within a Cavity	72
4.2.5	Avoid Picture Framing	76
4.2.6	Integral Hinges	78

4.2.7	Balanced Filling throughout a Mold	81
4.2.7.1	Gating Position(s) within a Cavity	82
4.2.7.2	Multi-Cavity Molds	86
4.2.8	Provide for Uniform Temperatures (Mold and Melt)	89
4.2.9	Eliminate, Strategically Place, or Condition Welds	90
4.2.10	Avoiding Flow Hesitation	91
4.2.11	Managing Frictional Heating of the Melt	93
4.2.12	Minimize Runner Volume in Cold Runners	93
4.2.13	Avoid Excessive Shear Rates	94
4.2.14	Avoid Excessive, and Provide for Uniform Shear Stresses	96
5	The Melt Delivery System	99
5.1	Runner Design Fundamentals	99
5.2	Overview of Runner/Melt Delivery System	100
5.2.1	Machine Nozzle	101
5.2.1.1	Nozzle Filter	102
5.2.1.2	Static Mixers	103
5.2.2	Sprue	103
5.2.3	Runner	103
5.2.4	Gate	104
5.3	Melt Flow through the Melt Delivery System	104
5.3.1	Melt Preparation – The Injection Molding Machine	104
5.3.1.1	Pressure Development from a Molding Machine	105
5.3.1.2	Flow through a Runner Channel	106
5.3.2	Effect of Temperature on Flow	107
5.3.2.1	Melt Temperature	107
5.3.2.2	Mold Temperature	109
5.3.3	Cold vs. Hot Runners	110
5.3.4	Pressure Drop through the Melt Delivery System (Nozzle vs. Sprue vs. Runner vs. Gate vs. Part Forming Cavity)	110
5.4	Use of Mold Filling Analysis	111
5.5	Runner Cross-Sectional Size and Shape	113
5.5.1	The Efficient Flow Channel	113
5.5.2	Pressure Development in the Runner	113
5.5.2.1	Flow through a Hot Runner vs. a Cold Runner	117
5.5.3	Runner Effect on Cycle Time	117
5.5.3.1	Cold Runner and Sprue Cooling Time	117
5.5.3.2	Hot Runner	118
5.5.4	Constant Diameter vs. Graduated Diameter Runners	118

5.6	Designing Runners for Shear- and Thermally-Sensitive Materials	121
5.7	Runner Layouts	122
5.7.1	Geometrical Balanced Runners	122
5.7.2	Non-Geometrically Balanced Runners	125
5.7.3	Fishbone Runners vs. Geometrically Balanced Runners	125
5.7.3.1	Flow Balance Ratio	127
5.7.3.2	Melt Variation in Unbalanced Molds	128
5.7.3.3	Artificial Balancing of Runners	128
5.7.3.4	Do the Artificially Balanced Runners Reduce Runner Volume?	131
5.7.4	Family Molds	135
6	Filling, Melt, and Product Variations Developed in Multi-Cavity Molds	137
6.1	Sources of Product Variation in Multi-Cavity Molds of Mold Filling Imbalances	138
6.1.1	Product Variations Resulting from the Runner Design	138
6.1.2	Product Variations Resulting from Non-Runner Layout Issues	140
6.2	Imbalance Effects on Process, Product, and Productivity	144
6.2.1	Artificial Balancing of Runners	148
6.3	Shear-Induced Melt/Molding Variations from Geometrically Balanced Runners	150
6.3.1	Development and Stratification of Melt Variations Across a Runner Channel	150
6.3.2	Laminate Separation in Branching Runners Causing Cavity-to-Cavity Product Variations	152
6.3.3	Shear-Induced Melt Imbalances in Stack Molds	157
6.3.4	Development of Intra-Cavity Variations and Influence on Residual Stresses and Warpage	158
6.3.4.1	Warpage	164
6.3.4.2	Core Deflection	166
6.3.4.3	Effect on Concentric Parts (Gears, Fans, and Others)	167
6.3.5	Alternative Theories of the Cause of Mold Filling Imbalances	168
6.3.5.1	Cooling Variations	169
6.3.5.2	Plate Deflection	169
6.3.5.3	Corner Effect of Branching Runners	170
6.3.5.4	Melt Pressure as the Cause of Filling Imbalance	172
6.4	Runner Layouts	172
6.4.1	Identification of Various Flow Groups in Common Geometrically Balanced Runners	173

6.4.2	Apparent Geometrically Balanced Runner Layouts	175
6.5	Effect of Shear-Induced Melt Variations on Two-Stage Injection Processes ..	176
6.5.1	Gas Assist Injection Molding	176
6.5.2	Co-Injection Molding	179
6.5.3	Structural and Microcellular Foam Molding	181
6.6	The Cost of Melt Imbalances	182
7	Managing Shear-Induced Melt Variations for Successful Molding	185
7.1	Static Mixers	186
7.2	Artificial Balancing	188
7.2.1	Varying Sizes of Branching Runners or Gates to Achieve a Filling Balance	188
7.2.2	Varying Temperatures to Control Filling Balance	189
7.3	Melt Rotation Technology	190
7.3.1	Melt Rotation Technology in Hot Runner Molds	197
7.3.2	Melt Rotation Technology in Cold Runner Molds	198
7.3.3	Melt Rotation for Intra-Cavity Imbalances	199
7.3.4	Multi-Axis Melt Symmetry	200
7.3.5	In-Mold Adjustable Rheological Control (iMARC™)	202
7.3.5.1	3D Molding	203
7.4	Melt Rotation for Controlling Two Stage Injection Processes	207
7.5	Controlling Warpage through Melt Rotation Technology	209
7.5.1	Development of Warpage Potential	211
7.5.2	Controlled Warpage through Melt Rotation Technology	214
7.5.3	New Application for 3D Molding	216
7.6	MeltFlipper® Melt Rotation Technologies	217
7.6.1	Important MeltFlipper Patent Issues	217
7.6.2	Melt Rotation in Cold Runner Molds	218
7.6.3	Melt Rotation Technology in Hot Runner Molds	220
7.6.4	Multi-Axis Melt Symmetry	220
7.6.5	In-Mold Adjustable Rheological Control (iMARC™)	222
8	Cold Runner Molds	225
8.1	Sprue	226
8.1.1	Cold Sprue	227
8.1.2	Hot Sprue	232
8.2	The Cold Runner	233

8.2.1	Important Machining Considerations	235
8.2.2	Sizing of Runners	235
8.2.3	Venting	236
8.2.4	Runner Ejection	237
8.2.4.1	Sprue Puller	237
8.2.4.2	Secondary Sprue/Cold Drop	238
8.2.4.3	Runner	238
8.2.5	Cold Slug Wells	239
8.3	Runners for Three-Plate Cold Runner Molds	240
8.4	Gate Designs	244
8.4.1	Sprue Gate	245
8.4.2	Common Edge Gate	246
8.4.3	Fan Gate	247
8.4.4	Film Gate or Flash Gate	248
8.4.5	Ring Gate	249
8.4.6	Diaphragm (Disk) Gate	250
8.4.7	Tunnel Gate	252
8.4.8	Cashew or Banana Gate	254
8.4.9	Jump Gate	255
8.4.10	Pin Point Gate	256
8.4.11	Chisel Gate	257
8.4.12	Overflow Gate	257
8.5	Effects of Gate Diameter in Multi-Cavity Molds	258
8.5.1	Study 1	258
8.5.2	Study 2	259
8.5.3	Measuring Tolerances	262
9	Hot Runner Molds	267
9.1	Overview	267
9.1.1	Advantages and Disadvantages of Hot Runner Systems	268
9.1.1.1	Advantages of Hot Runners	268
9.1.1.2	Disadvantages of Hot Runners	270
9.1.1.3	Summary of Attributes of Different Runner Systems	271
9.2	Overview of Multi-Cavity Hot Runner Systems (Contrasting Systems)	272
9.2.1	Externally Heated Manifold and Drops/Nozzles	273
9.2.2	Externally Heated Manifold with Internally Heated Drops	274
9.2.3	Internally Heated Manifold and Internally Heated Drops	275
9.2.4	Insulated Manifold and Drops	276
9.3	Stack Molds	278

10	Hot Runner Flow Channel Design	281
10.1	Layout for Balanced Molding	282
10.2	Cross-Sectional Shape	284
10.3	Corners	284
10.3.1	Drilled Runner Channels	285
10.3.2	Machined Laminate Plate Runner Channels	287
10.4	Effect of Diameter	287
10.4.1	Pressure	287
10.4.2	Shot Control	290
10.4.3	Color Change	291
10.4.4	Material Change	294
11	Hot Runner Drops, Nozzles, and Gates	295
11.1	Hot Drops	296
11.1.1	Externally Heated Hot Drops (Nozzles)	297
11.1.2	Internally Heated Hot Drops	298
11.1.3	Heat Conducting Nozzles	299
11.2	Restrictive/Pin Point Gates	300
11.3	Gate Design Considerations	302
11.3.1	Gate Freeze-Off	302
11.3.2	Stringing/Drooling	303
11.3.3	Packing	304
11.3.4	Nozzle Tips for Hot Runner Thermal Gates	305
11.3.4.1	Ported Tips	306
11.3.4.2	Torpedo-Style Tips	308
11.3.5	Mechanical Valve Gates	309
11.3.5.1	Consideration of Valve Pin Flow Restrictions	312
11.3.5.2	Sequential Valve Gates	313
11.3.5.3	Valve Pin Movement Control for Sequential Gating	315
11.3.6	Thermal Shut-Off Gates	321
11.3.7	Hot Edge Gates	322
11.3.8	Multi-Tip Nozzles	323
11.4	Special Nozzle Arrangement	324
12	Thermal Issues of Hot Runner Systems	327
12.1	Heating	327
12.1.1	Coil (Cable) Heaters	328
12.1.2	Band Heaters	328
12.1.3	Tubular Heaters	329

12.1.4	Cartridge Heaters	330
12.1.5	Heat Pipe Technology	330
12.2	Heater Temperature Control	331
12.2.1	Thermocouples	331
12.2.2	Temperature Controllers	332
12.3	Power Requirements	334
12.4	Thermal Isolation of the Hot Runner	335
12.5	Gate Temperature Control	338
12.5.1	Gate Heating	340
12.5.2	Gate Cooling	340
13	The Mechanics and Operation of Hot Runners	341
13.1	Assembly and Leakage Issues	341
13.1.1	System Design	342
13.1.2	Hot Runner System Machining and Assembly	347
13.2	Mold and Machine Distortions	353
13.3	Startup Procedures	355
13.4	Color and Material Changes	355
13.5	Gates	356
13.5.1	Vestige	356
13.5.2	Clog	356
13.5.3	Wear	357
13.6	Maintenance	357
14	Process of Designing and Selecting a Runner System (Gate and Runner) – A Summary	359
14.1	Number of Gates	359
14.2	Gating Position on a Part	359
14.2.1	Cosmetic	359
14.2.2	Effect on Shrinkage, Warp, and Residual Stress	360
14.2.2.1	Orientation	360
14.2.2.2	Volumetric Shrinkage (Regional)	360
14.2.2.3	Unbalanced Filling	361
14.2.3	Structural Issues	361
14.2.3.1	Gate Stress	361
14.2.3.2	Flow Orientation	361
14.2.4	Gating into Restricted, or Otherwise Difficult to Reach Locations ...	362

14.3	Cavity Positioning	362
14.4	Material	362
14.5	Jetting	362
14.6	Thick vs. Thin Regions of the Part	363
14.6.1	Volumetric Shrinkage	363
14.6.2	Hesitation	363
14.7	Number of Cavities	363
14.8	Production Volume	363
14.9	Precision Molding (Precision Size, Shape, Weight, Mechanical Properties, and Consistency)	364
14.10	Color Changes	364
14.11	Material Change	365
14.12	Regrind of Runners	365
14.13	Part Thickness	365
14.13.1	Thin Part	365
14.13.2	Thick Part	366
14.14	Part Size	366
14.15	Labor Skill Level	366
14.16	Post Mold Handling	367
14.17	Part/Gate Stress Issues	367
14.18	Hot and Cold Runner Combinations	367
14.19	Two-Phase Injection Processes	367
15	Troubleshooting	369
15.1	Flow Grouping Mold Diagnostics	369
15.1.1	Shear-Induced Flow Imbalance Developed in a Geometrically Balanced Runner	370
15.1.2	Steel Variations in the Mold	371
15.1.3	Cooling Effects	371
15.1.4	Hot Runner Systems	371
15.1.5	Summary of Test Data	371
15.1.6	Flow Grouping: Method of Application	372
15.2	Injection Molding Troubleshooting Guidelines for Scientific Injection Molding	375
15.3	Injection Molding Process Development	418
15.3.1	The Molding Process	418

15.3.1.1	Mold Cooling	419
15.3.1.2	Clamp Unit – Initial Settings	420
15.3.1.3	Injection Unit – Initial Settings	422
15.3.1.4	Fill Time Scan – Evaluating First Stage Flow Rate	424
15.3.1.5	Pack Scans – Evaluating Second Stage Pack Pressure and Pack Time	430
15.3.1.6	Evaluate Cushion, Cooling Time, and Cycle Time	434
15.3.2	Process Monitoring and Process Documentation	436
15.4	List of Amorphous and Semi-Crystalline Resins	440
Index	443